

NEW HEADQUARTERS BUILDING
Construction Progress Report
18 February 1963

Main Building

STATINTL

STATINTL Building Access for [] The "SERVICE" badges which
STATINTL previously allowed [] unescorted access were rescinded 1 February.
STATINTL Since then visits by [] to investigate air conditioning
problems and follow-up punch list items have been severely curtailed because
it is impractical to escort them around the building. The Office of Security will
expedite their clearance for no-escort access, but it will require a minimum
of 30 days. Their personal history statements are now being submitted.

C
O
P
Y

TRANSMITTAL SLIP		DATE <i>11. 14 63</i>
TO: <i>Colonel Edwards</i>		
ROOM NO.	BUILDING	
REMARKS: <i>The problem raised by Col. White has been taken care of.</i>		
FROM: <div style="border: 1px solid black; width: 200px; height: 30px; display: inline-block;"></div>		
ROOM NO.	BUILDING	EXTENSION

FORM NO. 241
1 FEB 55

REPLACES FORM 36-8
WHICH MAY BE USED.

GPO : 1957-O-439445 (47)

STATINTL